


# Major Debris Disaster Cases Express – Other, 2015

104 Other

## Nantou County—Chingying Village, Ren'ai Township



(Reference Rainfall Station : Lushan(C01010) Warning threshold : 250mm)

### Chingying Village, Ren'ai Township

- ❖ Disaster Location : 7K at Provincial Highway 85
- ❖ Disaster Time : 05:00, Aug, 1<sup>st</sup>
- ❖ Disaster Type : Collapse
- ❖ Accumulated Rainfall : 0 mm

Provincial Highway 85 is the main access for Hetzuo Village. There started to take place some small-scale landslide around 7K of Provincial Highway 85 from July. On 5:00, August 1<sup>st</sup>, it extended to a large-scale landslide. The debris buried the access road for 50 meters where interrupted the traffic and 2000 residents were affected. The landslide area was 7500m<sup>2</sup> with 45000m<sup>3</sup> debris.

- #1 : Metadata standard: TWD 97 system
- #2 : Data resource: SWCB
- #3 : The shooting angles was based on the magnetic north 0 degree, moving clockwise to measure the horizontal angles of target

